

Facts About...

Site photos-Former Contee Sand and Gravel Site
(State Master List)



Photo 1: Removal of contaminated soil from Lagoon 4. Photo Courtesy: CSI 2009 Remedial Action Report (RAR)



Photo 2: View of Lagoon 4 facing NE during remediation. Photo Courtesy: CSI, 2009 RAR



Photo3: View of Lagoon 3 during remediation. Photo Courtesy: CSI, 2009 RAR



Photo 4: View of Lagoon 2, facing south. Remediation was done up to the edge of the landfill. Photo Courtesy: CSI, 2009 RAR



Photo 5: One of the two staging areas, where all the excavated material was stockpiled, prior to being characterized into hazardous or non-hazardous material. Photo Courtesy: CSI



Photo 6: Remediation activity under the storm water pipe going through the lagoon 4, Photo Courtesy: CSI 2010, RAR



Photo 7: Remediation activity in the lagoon 1, Photo Courtesy: CSI, 2010 RAR



Photo 8: Contaminated material excavated from lagoon 4, Photo Courtesy: CSI, 2010 RAR



Photo 9: Remediation activity in the lagoon 3, Photo Courtesy: CSI, 2010 RAR



Photo 10: Remediation activity in the lagoon 4, Photo Courtesy: CSI, 2010 RAR



Photo 11: Remediation activity in the lagoon 2, Landfill can be seen on the right Photo Courtesy: CSI, 2010 RAR



Photo 12: View of Lagoon 4 after remediation and site stabilization, Photo Courtesy: CSI, 2010 RAR



Photo 13: View of Lagoon 3 after remediation and site stabilization, Photo Courtesy: CSI RAR



Photo 14: View of Lagoon 2 after remediation and site stabilization, Photo Courtesy: CSI RAR




Photo 15: Contaminated product excavated from a lagoon in Contee, Photo Courtesy: CSI RAR